

Spicers Farmhouse

Etchingill, Folkestone,
Kent CT18 8DE

Schedule of Repairs - Internal Photos

November 2023

30681A

CLAGUE ARCHITECTS



01

Original chimney opening has been partially blocked in



02

Evidence of medieval window



03

Brickwork covering original chimney stack




04

Steep pitched staircase that replaces original



05

Studwork



06

Condition of chimney cross beams



07

Original chimney opening has been partially blocked in & hidden by hearth



08

Corner post to be repaired



09

19th century chimney stack



10

19th century chimney stack



11

Odd arrangement at first floor landing



12

Original opening covered by hearth